



United States Steel Corporation
Clairton Works
400 State Street
Clairton, PA 15025

Jan
5/25

May 15, 2006

Dr. Roger C. Westman
Department of Air Quality
Bureau of Air Pollution Control
301 Thirty-Ninth Street
Pittsburgh, PA 15201

U.S. Environmental Protection Agency
Region III
Air, Radiation & Toxics Division
1650 Arch Street
Philadelphia, PA 19103-2029
ATTN: James W. Hagedorn (3AT23)

Assistant Council
Department of Environmental Protection
Southwest Region
400 Waterfront Drive
Pittsburgh, PA 15222-4745
ATTN: Steve Hepler

Department of Justice
Environmental and Natural Resource Division
Environmental Enforcement Section
P.O. Box 7611
Ben Franklin Station
Washington, D.C. 20044
ATTN: David Street, Esq.

Subject: USS Reference Number: 06-0169
ACHD Reference Number: 7531
Sulfur Plant
USS Clairton Works

Gentlemen:

The attached form terminates the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

Sincerely,

Anton Lukac
Plant Manager
Clairton Works

NOTICE OF OUTAGE OF EQUIPMENT
ARTICLE XXI - SECTION 2108.1

1. **USS Reference Number:** 06-0169 Termination
ACHD Reference Number: 7531
2. **Date & Time of Breakdown:** Date: 04/19/06 Time: 1120 hours
3. **Company Name:** U.S. Steel Corporation - USS Clairton Works
4. **Specific Equipment Involved or Affected:** Sulfur Plant
5. **BAPC Permit Number (if applicable):**
6. **Location:** Clairton, PA
7. **Nature and cause of breakdown:** The 101J spare sulfur plant stripper vacuum axi was unavailable for service due to a seized axi compressor. The 101J Axi is a redundant piece of equipment. The spare C658 Axi carried the full load.

Sulfur Plant performance will not be affected. Sulfur emissions will not increase.
8. **Identification of Emissions:**
 - A. **Type(s)** (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
The spare C658 Axi carried the full load. No environmental impact is expected.
 - B. **Toxic qualities of each type** (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A No environmental impact is expected.
 - C. **Amount of each type emitted (or likely to be emitted).**
N/A
9. **Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).**
The spare C658 Axi carried the full gas flow to the plant.
10. **Facility back in operation -** Date: 05/04/06 Time: 0900 hours

Signature Coleen M. Davis Date 5/18/06
Coleen M. Davis
Senior Environmental Control Engineer Phone: 233-1015